

Five Star Auto Repairing Garage

Report on Job History From 01/01/2017 To 04/10/2022 (DETAIL)

Date : 04/10/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
November 2017							
[REDACTED]							
IN201711-188	82492	19682 DXB-K	(Makemodel:Lincon / Chassisno:9Y89S647025 Odometer:49630)				
Owner Name	[REDACTED]						
			LABOUR				
				Removed radiator, repaired and refixed	1.00	200.00	200.00
				Fabricated brackets fixed both fan with necessary wirings	1.00	500.00	500.00
				Front and rear shock absorbers	1.00	600.00	600.00
				Cylinder head overhauled	1.00	1800.00	1,800.00
				Removed transmission, replaced crank rear oil seal and converter oil seal	1.00	700.00	700.00
				Underneath rust proofing	1.00	700.00	700.00
				Full polish	1.00	700.00	700.00
				Complete body paint touch up	1.00	800.00	800.00
				Fuel guage fixing	1.00	200.00	200.00
				Wheel rim painting (4 @ 100)	4.00	100.00	400.00
				Replaced water pump	1.00	350.00	350.00
				Replaced A/c. compressor,	1.00	250.00	250.00
			GAS OIL				
				Flushed complete system, pressure tested vaccumed and A/c. gas filled	1.00	400.00	400.00
				Full lubrication servicing done, changed oil and filter, checked and top up all oil levels and water levels	1.00	200.00	200.00
			PARTS				
				Battery	1.00	400.00	400.00
				Water pump	1.00	1050.00	1,050.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2017 To 04/10/2022 (DETAIL)

Date : 04/10/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Oil Pan gasket	1.00	170.00	170.00
				AT oil pan gasket	1.00	150.00	150.00
				AT Filter	1.00	225.00	225.00
				Valve cover gasket	1.00	140.00	140.00
				Crankshaft front oil seal front & rear	2.00	150.00	300.00
				Torque Converter seal	1.00	160.00	160.00
				O ring	4.00	20.00	80.00
				Belt	1.00	40.00	40.00
				Brake hose	4.00	120.00	480.00
				A/c. condensor fan (used)	1.00	250.00	250.00
				Thermostat valve	1.00	140.00	140.00
				Head gasket kit	1.00	1200.00	1,200.00
				Spark plugs	8.00	15.00	120.00
				A/c fan (used - Nissan)	1.00	150.00	150.00
				Temperature guage	1.00	280.00	280.00
				A/c. Compressor	1.00	1550.00	1,550.00
				Coolant and additive	1.00	150.00	150.00
				Radiator cap	1.00	50.00	50.00
				Shock Absorbers	4.00	250.00	1,000.00
			GAS OIL				
				ATF oil	10.00	25.00	250.00
			SUBLET				
				Interior cleaning	1.00	450.00	450.00
				Towing charges to Al Barsha	1.00	120.00	120.00

Five Star Auto Repairing Garage

Report on Job History From 01/01/2017 To 04/10/2022 (DETAIL)

Date : 04/10/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Towing charges to Five star	1.00	120.00	120.00
				Passing	1.00	140.00	140.00
				Veh. reg.	1.00	450.00	450.00
				A/c. compressor clutch repaired	1.00	225.00	225.00
				Central lock and remote control fixing	1.00	400.00	400.00
				Wheel allignment	1.00	150.00	150.00
				Driving shaft cross opening & fitting (Machining charges)	1.00	120.00	120.00
				Tyres	4.00	340.00	1,360.00
				Cylinder head pressure test, facing, head seat and valve grinding, cylinder head place new making, guide making,etc.	1.00	1050.00	1,050.00
				Radiator service	1.00	250.00	250.00
				Wheel rim polish	4.00	250.00	1,000.00
			OTHERS				
				Consumables	1.00	150.00	150.00
				Petrol : 29/08/17	1.00	100.00	100.00
				Petrol : 04/11/17	1.00	100.00	100.00
				Petrol : 12/11/17	1.00	100.00	100.00
				Total :			22,420.00
				dvance : 5,000.00			
				Discount : 66.00			
				Net :			17,354.00

June 2018

IN201806-183 86654 19682 DXB-K (Makemodel:Lincon / Chassisno:9Y89S647025 Odometer:19682)

Owner Name [REDACTED]

LABOUR

Five Star Auto Repairing Garage

Report on Job History From 01/01/2017 To 04/10/2022 (DETAIL)

Date : 04/10/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Repaired starting trouble, replaced ignition coil, module and pick up coil	1.00	400.00	400.00
			PARTS				
				Ignition Coil	1.00	450.00	450.00
				Pick up coil	1.00	450.00	450.00
				Ignition control module	1.00	645.00	645.00
			SUBLET				
				Towing charges	1.00	125.00	125.00
						Total :	2,070.00

September 2018

██████████

IN201809-125 87732 19682 DXB-K (Makemodel:Lincon / Chassisno:9Y89S647025 Odometer:)

Owner Name ██████████

LABOUR

Replaced battery	1.00	21.00	21.00
------------------	------	-------	-------

PARTS

Battery	1.00	360.00	360.00
---------	------	--------	--------

Total : 381.00

November 2018

██████████

IN201811-42 88550 19682 DXB-K (Makemodel:Lincon / Chassisno:9Y89S647025 Odometer:52070)

Owner Name : ██████████

Five Star Auto Repairing Garage

Report on Job History From 01/01/2017 To 04/10/2022 (DETAIL)

Date : 04/10/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
			LABOUR				
				Removed A/c. valve, cleaned and refixed			300.00
			GAS OIL				
				Flushed complete system, pressure tested, vaccumed and A/c.gas filled			300.00
						Total :	600.00
					Discount :	28.57	Net :
							600.00

December 2018

██████████

IN201812-119 88836 19682 DXB-K (Makemodel:Lincon / Chassisno:9Y89S647025 Odometer:52190)
 Owner Name ██████████

			LABOUR				
				Carburator overhauled			950.00
			PARTS				
				Carburator kit	1.00	740.00	740.00
			OTHERS				
				Petrol	1.00	175.00	175.00
						Total :	1,865.00

May 2019

██████████

IN201905-143 91017 19682 DXB-K (Makemodel:Lincon / Chassisno:9Y89S647025 Odometer:53387)
 Owner Name : ██████████

SUBLET

Five Star Auto Repairing Garage

Report on Job History From 01/01/2017 To 04/10/2022 (DETAIL)

Date : 04/10/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount	
				Towing charge	1.00	150.00	150.00	
				Repaired bolt and nut new made for he rear suspension	1.00	100.00	100.00	
						Total :	250.00	
					Discount :	0.48	Net :	262.00

Five Star Auto Repairing Garage

Report on Job History From 01/02/2021 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
February 2021							
[REDACTED]							
IN202102-213	97602	60708 DXB-K	(Makemodel:Lincon / Chassisno: Odometer:55563)				
Owner Name	[REDACTED]						
			LABOUR				
				Overhauled power steering	1.00	400.00	400.00
				Replaced crank front oil seal	1.00	250.00	250.00
				Removed transmission assly, replaced crank rea roil seal and converter oil seal	1.00	900.00	900.00
				Removed engine oil pan, repalced gasketsand refixed (pull up the engine)	1.00	500.00	500.00
				Removed rake booster cylinder and refixed	1.00	350.00	350.00
				Removed transmission oil pan, repaired booster, replaced AT filter and gasket	1.00	550.00	550.00
			GAS OIL				
				Full lubrication service	1.00	250.00	250.00
			PARTS				
			SUBLET				
				Brake booster overhaul charge	1.00	550.00	550.00
				Steam wash	1.00	160.00	160.00
				Wheel balancing	1.00	200.00	200.00
			PARTS				
				Oil pan gasket	1.00	220.00	220.00
				Transmission filter and gasket	1.00	220.00	220.00
				Power steering box kit	1.00	320.00	320.00
				Oil seal	1.00	145.00	145.00

Five Star Auto Repairing Garage

Report on Job History From 01/02/2021 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
				Crank front oil seal	1.00	220.00	220.00
				Crank rear oil seal	1.00	190.00	190.00
				Orings	1.00	30.00	30.00
				Oil seal (front crank rear seal)	1.00	40.00	40.00
				Gasket sealant	1.00	100.00	100.00
				ATF	1.00	250.00	250.00
				Oil seal	1.00	60.00	60.00
			OTHERS				
				Consumables	1.00	100.00	100.00
						Total :	6,005.00
					Discount :	290.71	Net :
							6,000.00

January 2022

IN202201-29 101102 60708 DXB-K (Makemodel:Lincon / Chassisno: Odometer:56323)
 Owner Name [REDACTED]

LABOUR

Replaced rear rh chrome pannel with painting 350.00
 Removed front disc brake disc skimmed and refixed 200.00

SUBLET

Machining charges for brake disc skimming 2.00 30.00 60.00

PARTS

Cost of chrome pannel 1.00 2642.00 2,642.00
 (shipping 630+195, cutoms and vat 239, parts 1578)

Five Star Auto Repairing Garage

Report on Job History From 01/02/2021 To 30/09/2022 (DETAIL)

Date : 30/09/2022

Document ID	Job Ref	Reg No	Job Type	Item/Job Description	Qty	Rate	Amount
						Total :	3,252.00
						Discount :	0.57
						Net :	3,414.00

February 2022

██████████

IN202202-68 101431 60708 DXB-K (Makemodel:Lincon / Chassisno: Odometer:56441)

Owner Name ██████████

LABOUR

Replaced rear both side brake hose and system bleeding	1.00	350.00	350.00
Repaired rear Lhs shock absorber	1.00	250.00	250.00
Engine oil topup	1.00	150.00	150.00

PARTS

Brake hose 2x150	2.00	150.00	300.00
------------------	------	--------	--------

GAS OIL

Brake fluid	1.00	70.00	70.00
-------------	------	-------	-------

OTHERS

Consumables	1.00	20.00	20.00
-------------	------	-------	-------

SUBLET

Tyre 4x330	4.00	330.00	1,320.00
------------	------	--------	----------

Total : 2,460.00

Discount : 31.42 Net : 2,550.00



FIVE STAR
AUTO REPAIRING GARAGE
خمسة نجوم
مرآب تصليح السيارات

TRN : [REDACTED]

TAX-INVOICE

No. : IN202210-203
Date : 25/10/2022

To, [REDACTED] Dubai, UAE. Contact Person : [REDACTED] Staff ID : Email ID : [REDACTED] TRN No : Telephone : [REDACTED]	Reg. No. : 60708 DXB-K Year : Make / Model : Lincon / Chassis No. : Odometer : 57004 Driver Customer Name : [REDACTED] Tel. : [REDACTED] Vehicle Ref ID : Estimate No./ Dt : LPO No. / Dt : Job. Ref. / Date : 104018 20/10/2022
--	--

S.No.	Description	Quantity	Unit Rate	Amount
LABOUR				
1	Full lube service 5 K	1.00	250.00	250.00
2	Replaced all drive belts	1.00	150.00	150.00
3	Replaced fan wiring	1.00	150.00	150.00
Total :				550.00
PARTS				
1	Drive belt - 60+65+65	1.00	190.00	190.00
Total :				190.00
GAS OIL				
1	AC gas top up	1.00	100.00	100.00
Total :				100.00
GROSS TOTAL :				840.00

NOTE : Tech Ramu ,Jiji

AED:EIGHT HUNDRED EIGHTY-TWO AND XX / 100

VAT (5%) : 42.00
Round Off (-) :
NET TOTAL : 882.00

Received vehicle to my entire satisfaction with all tools and accessories complete.

Bank Details: [REDACTED]

Customer [REDACTED]

shyla.s

Prepared By

We accepts no responsibility for payments made against this invoice unless cash stamp affixed and signed AND/OR evidenced by an official receipt.