

LIBERTY

Certified Service

MULTI-POINT VEHICLE INSPECTION

ACDelco

Name: Mr Ammar

Year/Model: 1993 Pontiac

VIN/ias

Repair Order #:

Date: April 10 2022 Odometer: 99785

Registration #: 83751 Dubai

Checked and OK

May Require Attention Soon

Requires Immediate Action

CHANGE ENGINE OIL AND FILTER

OIL AND FLUID CHECK & CONDITION

	YES	NO
Engine oil	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Power steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transfer case	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Coolant	<input checked="" type="checkbox"/>	<input type="checkbox"/>

UNDER HOOD

	YES	NO
Engine air filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Belts/Tensioners	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Hose (Engine, power steering & HVAC)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fuel system	<input checked="" type="checkbox"/>	<input type="checkbox"/>

UNDER VEHICLE

	YES	NO
Exhaust system components	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Shock and Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>
CV joints and axle boot	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine Cooling system Leak	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Control arms & Steering linkages	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Steering gear box	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Drive and Propeller shaft	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine and Transmission mounts	<input checked="" type="checkbox"/>	<input type="checkbox"/>

TIRES AND TREAD DEPTH

Tire tread depth	4mm & above	2.4mm to 4mm	2.4mm & below	Pressure
Front LH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	32 PSI
Front RH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	34 PSI
Rear LH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	34 PSI
Rear RH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	34 PSI
Spare	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	32 PSI

OPEN FIELD ACTION

BATTERY CHECK

	YES	NO
Battery health	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Battery cable	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Battery Terminals	<input checked="" type="checkbox"/>	<input type="checkbox"/>



WIPER BLADES

	YES	NO
Right Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Left Front	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Rear	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Wind Shield	<input checked="" type="checkbox"/>	<input type="checkbox"/>



GENERAL CONDITION

	YES	NO
Interior lights and Gauges	<input checked="" type="checkbox"/>	<input type="checkbox"/>
External lights and Indicators	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Head lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Warning indication / lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Infotainment	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Restraint System	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Compartment air-filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>

BRAKE LINING

Lining thickness	7mm & above	4mm to 6mm	3mm & below
Front LH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front RH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear LH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear RH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Lowest lining	Front 6 mm	Rear 6 mm	

VEHICLE BODY CONDITION



Additional Recommended Services

Recommend to change wiring exterior door to hi-Resistance.

Service Consultant: _____

Technician: Ronald