

Kanzen Motorsports

Warehouse 3, Plot 8, 31st Street

Al Quoz Industrial Area 4 – Dubai

Tel: +971 58 515 2496


Email: info@kanzenmotorsports.com



Name: <u>NoLemons</u>	Phone:
-----------------------	--------

Received By	<u>Imesh</u>
Make	<u>Toyota</u>
Model	<u>Land Cruiser 7988</u>
Plate #	
Chassis/Vin #	<u>FJ62097023</u>
Mileage	<u>434475 KM</u>
Registration Exp.	
Received T/D	<u>8th December 2022</u>
Delivered T/D	<u>8th December 2022</u>

Please ensure that you removed all personal belongings from the vehicle. The garage will not be responsible for any missing items.



Comments:


T&C

We do not accept any responsibility for any damage/scratches reported/claimed without mutual inspection performed. T&C apply.

Client

Mechanical and visual inspection

Description	Minor	Bad	Critical
Change clutch fluid	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Power steering pump oil leak	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Rear sway bar link bush crack both side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission mount broken	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Front crank oil seal leak	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Change Engine mount	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission filler cap oil leak	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear and front shackle bushing crack both side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>





Overall Report

Exterior	Critical	Minor	OK	Engine	Critical	Minor	OK	Vehicle Half Raised	Critical	Minor	OK
Body Damage			✓	Brake Fluid Cond.			✓	Front Brake Pads			✓
Headlights			✓	Brake Fluid Leaks			✓	Front Brake Rotors			✓
Taillights			✓	P/S Condition		✓		Rear Brake Pads			✓
Wipers			✓	P/S Leaks	✓			Rear Brake Rotors			✓
Door Locks			✓	Coolant Cond.			✓	Parking Brake Pads			✓
Lubricate Hinges			✓	Coolant Leaks	✓			Brake Hose Cond.			✓
Electric Tailgate			✓	Engine Oil Cond.			✓	Wheel Guards			✓
Windows			✓	Engine Oil Leaks		✓		Wheel Bearing			✓
Interior	Critical	Minor	OK	Washer Fluid Level			✓	Tire Pressure			✓
Dash functions			✓	Washer Fluid Leaks			✓	Underbody	Critical	Minor	OK
Radio			✓	Engine Hoses		✓		Chassis Damage			✓
Windows			✓	Aux Belt -				Exhaust			✓
A/C & Heating			✓	Timing Belt -				Fuel Tank			✓
Seatbelts			✓	Air Filter Cond.			✓	Fuel Lines			✓
Airbags -				Coolant Radiator			✓	Brake Lines			✓
Sunroof -				A/C Condenser			✓	Transmission			✓
Interior Lights			✓	Cooling Fans			✓	Front Differential			✓
Horn			✓	Fuel Filter			✓	Rear Differential			✓
Mirrors			✓	Starter Motor			✓	Driveshaft/Axles			✓
Service History			✓	Battery			✓	FL Suspension			✓
Headlining			✓	Alternator Charging			✓	FR Suspension			✓
Locks			✓	Wheels & Tires	Critical	Minor	OK	RL Suspension			✓
Convertible Roof			✓	Front Left			✓	RR Suspension			✓
Tool Kit			✓	Front Right			✓	Road Test	Critical	Minor	OK
Other Electrical Equip.			✓	Rear Left			✓	Abnormal Noises			
Other	Critical	Minor	OK	Rear Right			✓	Acceleration			
Keys			✓	Spare				Transmission/Shift			
Registration -				Compressor				Clutch			
License Plates -				Tire Sealant				Gauges			

Tire Check	Thread Depth, mm			Pressure	Manufacturer/Model	Size	Rim	Index
	Inner	Middle	Outer					
Left Front					Yokohama	31X10.50	R15	
Right Front					Yokohama	31X10.50	R15	
Right Rear					Yokohama	31X10.50	R15	
Left Rear					Yokohama	31X10.50	R15	
Spare								

Battery Check			
Brand	Type (Wet/AGM/Lithium/Carbon)	Date	Ah Rating
Yuasa	45-800	26h-V62Ah (20hr)	

J 08.12.22

Technician Signature / Date